

**From:** [REDACTED]  
**To:** [REDACTED]  
**Sent:** 7/13/2021 9:12:41 PM  
**Subject:** Re: Dixie Fire Sequence of Events

Thanks [REDACTED]

This needs to be an item on our next SIPT/PSS/HAWC call.

Very Respectfully,

[REDACTED]  
[REDACTED] | HAWC Manager  
Pacific Gas and Electric Company  
[REDACTED]

---

**From:** [REDACTED]  
**Sent:** Tuesday, July 13, 2021 9:03:13 PM  
**To:** [REDACTED]  
**Subject:** Dixie Fire Sequence of Events

All –

Some background on the sequence of events for the Dixie Fire as best I know it at this time:

- 1715 – Tman reported a fire near the Cresta Dam via Signal (messaging app) and requested someone call 911 to report – Source: [REDACTED]
- 1718 – CAL FIRE dispatched (no associated IRWIN at any time) – Source: [REDACTED]
- 1732 – @CAL FIRE Butte reported engines are responding to fire in the area of Camp Creek Road and Dixie Road in Jarbo Gap – Twitter
- 1735 – “Engines were rolling” - Unclear if these were CAL FIRE or SIPT; I suspect CAL FIRE – Source: [REDACTED]
- 1743 – @CAL FIRE Butte reported air attack located the fire, tankers have retardant around the fire, working to get ground resources as scene – Twitter
- ?? – Someone in the HAWC first made aware [REDACTED] is aware of the fire – Source: ?
- 1804 – Manager [REDACTED] reaches out in Daily Group Chat about the fire
- 1838 – Initial Epage sent

[REDACTED]  
-----  
[REDACTED]  
Supervisor  
Hazard Awareness and Warning Center  
Pacific Gas & Electric  
[REDACTED]

*Some of the measures included in this document, email, presentation, or study are contemplated as additional precautionary measures intended to further reduce the risk of wildfires.*